

Review of Power System Reclassification Events 1 May 2018 to 31 October 2018

February 2019

A report for the National Electricity Market

Important notice

PURPOSE

AEMO has prepared this report on its power system reclassification decisions in the National Electricity Market for the period 1 May 2018 to 31 October 2018 in accordance with clause 4.2.3A(i) of the National Electricity Rules.

DISCLAIMER

This document or the information in it may be subsequently updated or amended. This document does not constitute legal or business advice and should not be relied on as a substitute for obtaining detailed advice about the National Electricity Law, the National Electricity Rules, or any other applicable laws, procedures or policies. AEMO has made every effort to ensure the quality of the information in this document but cannot guarantee its accuracy or completeness.

Accordingly, to the maximum extent permitted by law, AEMO and its officers, employees and consultants involved in the preparation of this document:

- make no representation or warranty, express or implied, as to the currency, accuracy, reliability or completeness of the information in this document; and
- are not liable (whether by reason of negligence or otherwise) for any statements or representations in this document, or any omissions from it, or for any use or reliance on the information in it.

1. Introduction

This report sets out AEMO's reasons for decisions to reclassify *non-credible contingency events* as *credible contingency events* under clause 4.2.3A(g) of the National Electricity Rules (NER).

AEMO is required by clause 4.2.3A(i) of the NER to report on reclassification decisions every six months. This report covers the period from 1 May 2018 to 31 October 2018 (reporting period). The report includes:

- 1. An explanation of how AEMO applied the criteria established in accordance with clause 4.2.3B for each of these decisions.
- 2. AEMO's analysis of reclassification trends during the reporting period, and its appraisal of the appropriateness and effectiveness of the relevant criteria applied in the case of each reclassification decision.

In this document, a word or phrase in *this style* has the same meaning as given to that term in the NER. References to times in this report, unless otherwise specified, are to Australian Eastern Standard Time (AEST).

2. Overview

There was a total of 280 reclassification events in this reporting period, compared to 209 reclassification events during the previous winter reporting period (1 May 2017 to 31 October 2017).

All but one of the reclassifications were appropriately determined in accordance with the reclassification criteria in AEMO's Power System Security Guidelines SO_OP_3715¹, for bushfires, lightning, or other reasons.

AEMO notified *Market Participants*, via Market Notices (MNs)², of the reasons for reclassifying these *non-credible contingency events*.

3. AEMO's role

In general terms, the *power system* is operated such that it will remain in a *satisfactory operating state*³ following the loss of a single major *transmission* or *generation* element. These events are defined as *credible contingency events*⁴ and include:

- Unexpected loss of a single transmission line, transformer or reactive plant.
- Unexpected loss of a single generating unit.

¹ AEMO, Power System Security Guidelines. Power system operating procedures are available at: http://aemo.com.au/Electricity/National-Electricity-Market-NEM/Security-and-reliability/Power-system-operation.

² A Market Notice is an email notification issued in real time by AEMO to market participants. Market Notices are also published on AEMO's website at https://www.aemo.com.au/Electricity/National-Electricity-Market-NEM/Market-notices-and-events.

³ Refer to clause 4.2.2 of the NER

⁴ Refer to clause 4.2.3 of the NER.

AEMO considers the occurrence of these events to be reasonably possible (a *credible contingency event*). A *non-credible contingency event* is a *contingency event* other than a *credible contingency event*. Examples include:

- Three phase electrical faults.
- The trip of any busbar in the transmission network.
- The trip of more than one transmission element.
- The trip of *transmission plant* in a manner not considered likely (for example, a *transmission line* that trips at one end only).
- The trip of multiple generating units.

AEMO is not required to operate the *power system* with the capability to remain in a *satisfactory operating* state following *non-credible contingency events* (other than any *protected events*), as the likelihood of their occurrence is low.

AEMO must reclassify a non-credible contingency event as a credible contingency event if the risk of this event impacting the power system has become reasonably possible due to abnormal conditions. Abnormal conditions may include severe weather conditions, lightning, and bushfires⁵.

4. Reclassification criteria

AEMO has developed criteria for determining whether a *non-credible contingency event* should be reclassified as a *credible contingency event* (reclassification criteria). The reclassification criteria are specified in AEMO's Power System Security Guidelines SO_OP_3715. The reclassification criteria apply to:

- Bushfires.
- · Lightning.
- Other events (such as severe weather or other threats with the potential to impact multiple generating units, pollution, protection and control issues, the occurrence of a *non-credible contingency event*).

The following section analyses how AEMO reclassified *non-credible contingency events* using the reclassification criteria for the reporting period.

5. Reclassification events,1 May 2018 to31 October 2018

AEMO reclassified 280 events during the reporting period. Table 1 summarises these events.

⁵ Refer to clause 4.2.3A (a) of the NER.

Refer to Appendix A1 for a complete list of events.

Table 1 Reclassification events for period 1 May 2018 to 31 October 2018

| Criteria | Number of reclassification events | Incidence of contingency occurring during reclassification |
|------------------|-----------------------------------|--|
| Bushfires | 6 | 0 |
| Lightning | 224 | 0 |
| Other | 50 | 0 |
| Total for Period | 280 | 0 |

AEMO reclassified all bushfire and lightning events in accordance with the reclassification criteria specified in Section 11.3 and Section 11.4 of SO_OP_3715 respectively.

There were 50 events reclassified under other criteria according to Section 11.5 and 11.6 of SO_OP_3715. Most of these were reclassified due to either:

- Forecast abnormal weather conditions (such as severe weather warnings due to high wind or cyclones), or
- Occurrence of a non-credible contingency event while AEMO considered there was a reasonable possibility of reoccurrence.

There were no occurrences of events while they were reclassified as credible.


One reclassification under other criteria was not consistent with the reclassification criteria.

On 1 August 2018, Snuggery No.3 132/33 kV transformer and Mount Gambier No.2 132/33 kV transformer tripped. The trip of Mount Gambier transformer was unexpected, and it offloaded the South East – Mount Gambier 132 kV line. When Mount Gambier transformer was returned to service, AEMO reclassified the trip of Mount Gambier transformer and another network element in the local 132 kV network as a credible contingency event, based on advice from ElectraNet that the trip was due to unstable protection operation. AEMO cancelled the reclassification on 10 August 2018 when the protection issue had been rectified.

AEMO later identified that the event should not have been reclassified because it did not meet the definition of a *contingency event* - Mount Gambier transformer and the local 132 kV network are not classified as *transmission elements*.

Figure 1 shows the number of reclassification events per region for the reporting period. The NSW/Qld segment in the figure below is due to the reclassification impacting both NSW and QLD regions.

Figure 1 Reclassifications per region, 1 May 2018 to 31 October 2018



The historical trend of reclassification events is shown in Figure 2. The number of reclassification events increased for all categories during this reporting period compared to the previous winter reporting period (1 May 2017 to 31 October 2017).

The number of reclassifications due to lightning increased by 24% overall from 180 in the previous winter, to 224 for this reporting period. For Queensland, in particular, lightning reclassifications increased from 76 to 115 between the two periods. In addition, there were 23 lightning reclassifications for Bulli Creek to Dumaresq 330 kV lines since the lines were added to the vulnerable transmission line list for lightning reclassifications during this reporting period.

The main contributor for the increased number of other reclassifications was due to severe weather reclassifications in South Australia. This number increased from 18 in the previous winter to 42 for this reporting period.




Figure 2 Historical reclassification events, 2009-18

Appendix A2 lists all the reclassified elements and the number of times they were reclassified during the period 1 May 2018 to 31 October 2018.

6. Non-credible contingency events,1 May 2018 to31 October 2018

During the reporting period, 22 *non-credible contingency events* occurred. AEMO subsequently reclassified eight of these events as *credible contingency events*, because there was a risk of the event reoccurring.

Note that the following events cancelled within this reporting period were initially reclassified before the period, so are not listed in Appendix A1:

- Trip of Moorabool Sydenham No. 1 500 kV line at Sydenham end only on 27 March 2018.
- Trip of H67 Calliope River H8 Boyne Island 7145 132 kV line and Gladstone Unit 1 on 18 February 2018.

Appendix A3 lists all *non-credible contingency events* that occurred during the reporting period, and AEMO's assessment of whether to reclassify each event as credible. The rows highlighted in blue in Appendix A3 explain the contingency events corresponding to the reclassifications highlighted in blue in Appendix A1.

One non-credible contingency event occurred before the reporting period, but was reclassified within the period, so is listed in Appendix A1 and A3:

• Trip of Loy Yang A3 and Pelican Point GT 12 and ST 18 on 23 April 2018.

6.1 Queensland and South Australia separation event

The separation of Queensland and South Australia from the rest of the *National Electricity Market (NEM)* occurred on 25 August 2018. The initiating event was the simultaneous trip of both Queensland – New South Wales Interconnector (QNI) lines following a lightning strike at 13:11:39. The trip of QNI lines resulted in separation of the Queensland region from the rest of the NEM power system. This was followed by the separation of South Australia from the rest of the NEM.

Prior to this event on 25 August 2018, QNI was not considered vulnerable to lightning, as there was no 'probable' or 'proven' risk of lightning strikes impacting both lines in accordance with the lightning reclassification criteria. Accordingly, the simultaneous trip of both QNI lines was not reclassified as credible due to the storm activity in the area.

After the resynchronisation of Queensland, AEMO reclassified the simultaneous trip of the QNI lines as a credible contingency and applied reclassification constraints pending identification of the cause. AEMO cancelled the reclassification at 17:45 on 25 August 2018, after Powerlink advised that the cause of the simultaneous trip was lightning strikes to transmission infrastructure impacting both circuits.

AEMO's decisions on reclassification of QNI were appropriate and consistent with the published reclassification criteria in SO_OP_3715. The two QNI 330 kV lines from Bulli Creek terminal station in Queensland to Dumaresq terminal station in New South Wales were later included in the vulnerable transmission line list for lightning reclassifications, specified in SO_OP_3715. Between 25 August 2018 and the end of the reporting period, there were 23 reclassifications for the simultaneous loss of Bulli Creek to Dumaresq 330 kV lines.

AEMO did not reclassify the simultaneous non-credible loss of the South Australia – Victoria interconnector at Heywood as credible, as the Heywood Emergency Control Scheme (known as the EAPT scheme) had operated in accordance with its design criteria.

The published incident report⁶ has more details of the event.

7. Reclassification constraints

When AEMO reclassifies an event as a *credible contingency event*, it seeks to operate the *power system* so it stays in a *satisfactory operating state* should the *credible contingency event* occur. AEMO typically invokes constraint equations to manage the *power system* accordingly while an event is reclassified.

Appendix A4 lists the binding constraint equations during reclassification events over the reporting period. There were 13 reclassified events that resulted in binding constraint equations.

8. Conclusion

AEMO concluded that, during the reporting period:

- 1. AEMO's reclassification decisions were appropriate and consistent with the reclassification criteria, with one exception.
- 2. AEMO notified Market Participants of the reasons for reclassifying non-credible contingency events.
- 3. The number of reclassification events was materially higher than historical winter period averages.

⁶ AEMO, Final report – Queensland and South Australia system separation on 25 August 2018, available at: http://www.aemo.com.au/-/media/Files/Electricity/NEM/Market_Notices and Events/Power System Incident Reports/2018/Qld---SA-Separation-25-August-2018-Incident-Report.pdf.

A1. Reclassification events, 1 May 2018 to 31 October 2018

Please note:

- INDJI Indji Watch (INDJI) is a system that monitors live information feeds on hazards such as bushfires and displays their positions relative to the locations of transmission assets. It is also used to provide detection and location of cloud to ground lightning strikes across the NEM transmission system.
- BOM AEMO receives advice from the Bureau of Meteorology (BOM) when severe weather is forecast in regions that may impact the NEM transmission system.

The events highlighted in blue below occurred after they were reclassified as a credible contingency. Further details on the reclassifications highlighted blue can be found in Appendix A3.

Table 2 Reclassification events 1 May 2018 to 31 October 2018

| Start MN | Start | Actual End Date | End MN | Reclassified Equipment | Region | Reason | Source |
|-------------|--------------------|--------------------|-----------|---|---------|-----------|-------------------|
| 63930 | 17/08/2018 1100hrs | 17/08/2018 1320hrs | 63932 | Coffs Harbour to Lismore (89) 330 kV line and the Koolkhan to Lismore (967) 132 k V line | NSW | Bushfires | INDJI |
| 64002 | 25/08/2018 1515hrs | 26/08/2018 1745hrs | 64012 | Bulli Creek – Dumaresq 8L and 8M 330 kV line causing Queensland and South Australia system separation | NSW/QLD | Other | Event Occurred |
| 64118 | 7/09/2018 0805hrsh | 7/09/2018 0940hrs | 64131 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 64138 | 7/09/2018 2210hrs | 8/09/2018 0835hrs | 64151 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 64504 | 25/09/2018 0050hrs | 25/09/2018 1230hrs | 64518 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 64540 | 26/09/2018 1000hrs | 26/09/2018 0235hrs | 64553 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 64580 | 26/09/2018 1310hrs | 26/09/2018 1405hrs | 64593 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 64636 | 29/09/2018 0300hrs | 29/09/2018 0500hrs | 64637 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 64668 | 30/09/2018 0310hrs | 30/09/2018 0415hrs | 64669 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 64724 | 6/10/2018 1440hrs | 6/10/2018 1910hrs | 64738 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |

| Start MN | Start | Actual End Date | End MN | Reclassified Equipment | Region | Reason | Source |
|-------------|--------------------|--------------------|-----------|---|---------|-----------|-------------------|
| 64774 | 10/10/2018 1330hrs | 10/10/2018 2335hrs | 64779 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 64795 | 11/10/2018 1320hrs | 11/10/2018 2020hrs | 64802 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 64821 | 12/10/2018 1030hrs | 12/10/2018 1435hrs | 64831 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 64854 | 13/10/2018 0615hrs | 13/10/2018 0715hrs | 64855 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 64923 | 17/10/2018 1345hrs | 17/10/2018 1445hrs | 64937 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 64950 | 18/10/2018 0210hrs | 18/10/2018 0440hrs | 64952 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 64954 | 18/10/2018 1135hrs | 18/10/2018 1225hrs | 64970 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 64972 | 18/10/2018 1335hrs | 18/10/2018 1635hrs | 64983 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 65020 | 19/10/2018 1550hrs | 19/10/2018 1640hrs | 65033 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 65056 | 20/10/2018 1850hrs | 20/10/2018 2050hrs | 65058 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 65067 | 21/10/2018 0910hrs | 21/10/2018 1340hrs | 65071 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 65112 | 24/10/2018 1535hrs | 24/10/2018 1620hrs | 65114 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 65115 | 24/10/2018 1700hrs | 24/10/2018 1900hrs | 65116 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 65118 | 24/10/2018 2005hrs | 24/10/2018 2310hrs | 65121 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 65122 | 25/10/2018 1510hrs | 25/10/2018 1940hrs | 65126 | Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | Lightning | INDJI |
| 62719 | 5/05/2018 1855hrs | 5/05/2018 2220hrs | 62731 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 62724 | 5/05/2018 2010hrs | 5/05/2018 2155hrs | 62728 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 62950 | 26/05/2018 1105hrs | 26/05/2018 1950hrs | 62952 | Trip of Strathmore No. 1 and No. 2 132 kV buses | QLD | Other | Event Occurred |
| 63185 | 13/06/2018 1330hrs | 13/06/2018 1625hrs | 63188 | Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | Lightning | INDJI |
| 63310 | 2/07/2018 1255hrs | 2/07/2018 1455hrs | 63316 | Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | Lightning | INDJI |
| 63311 | 2/07/2018 1325hrs | 2/07/2018 1730hrs | 63319 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 63312 | 2/07/2018 1345hrs | 2/07/2018 1445hrs | 63313 | Bouldercombe – Rockhampton No. 7108 and Bouldercombe – Egans Hill No. 7221 132 kV lines | QLD | Lightning | INDJI |

| Start MN | Start | Actual End Date | End MN | Reclassified Equipment | Region | Reason | Source |
|-------------|--------------------|--------------------|-----------|---|--------|-----------|-------------------|
| 63315 | 2/07/2018 1455hrs | 2/07/2018 1555hrs | 63317 | Bouldercombe – Rockhampton No. 7108 and Bouldercombe – Egans Hill No. 7221 132 kV lines | QLD | Lightning | INDJI |
| 63593 | 25/07/2018 1640hrs | 25/07/2018 1840hrs | 63597 | Bouldercombe – Rockhampton No. 7108 and Bouldercombe – Egans Hill No. 7221 132 kV lines | QLD | Lightning | INDJI |
| 63595 | 25/07/2018 1810hrs | 25/07/2018 2210hrs | 63601 | Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | Lightning | INDJI |
| 63596 | 25/07/2018 1830hrs | 25/07/2018 2230hrs | 63602 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 63598 | 25/07/2018 1900hrs | 25/07/2018 2000hrs | 63599 | Bouldercombe – Rockhampton No. 7108 and Bouldercombe – Egans Hill No. 7221 132 kV lines | QLD | Lightning | INDJI |
| 63603 | 25/07/2018 2245hrs | 26/07/2018 0145hrs | 63604 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 63976 | 21/08/2018 0805hrs | 10/09/2018 1230hrs | 64167 | Trip of Unit 3 Stanwell Power station and any one of the individual 275 kV transmission lines connected to H29 Stanwell | QLD | Other | Event Occurred |
| 64004 | 25/08/2018 2015hrs | 25/08/2018 2115hrs | 64005 | Moranbah Goonyella 7369 and 7370 132 kV lines | QLD | Lightning | INDJI |
| 64006 | 25/08/2018 2135hrs | 25/08/2018 2235hrs | 64007 | Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | Lightning | INDJI |
| 64099 | 6/09/2018 0945hrs | 6/09/2018 1430hrs | 64101 | Ross to Chalumbin 857 & 858 275 kV transmission lines | QLD | Bushfires | INDJI |
| 64133 | 7/09/2018 1640hrs | 8/09/2018 1745hrs | 64161 | Ross to Chalumbin 857 & 858 275 kV transmission lines | QLD | Bushfires | INDJI |
| 64312 | 20/09/2018 0050hrs | 20/09/2018 0155hrs | 64314 | Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | Lightning | INDJI |
| 64313 | 20/09/2018 0050hrs | 20/09/2018 0155hrs | 64315 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 64520 | 25/09/2018 1320hrs | 25/09/2018 1725hrs | 64533 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 64534 | 25/09/2018 1735hrs | 25/09/2018 1840hrs | 64537 | Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | Lightning | INDJI |
| 64535 | 25/09/2018 1735hrs | 25/09/2018 1840hrs | 64536 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 64538 | 25/09/2018 1915hrs | 25/09/2018 2020hrs | 64539 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 64594 | 26/09/2018 1515hrs | 26/09/2018 2020hrs | 64597 | Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | Lightning | INDJI |
| 64596 | 26/09/2018 1745hrs | 26/09/2018 2020hrs | 64598 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 64600 | 27/09/2018 1435hrs | 27/09/2018 1540hrs | 64601 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 64602 | 27/09/2018 1615hrs | 27/09/2018 1715hrs | 64605 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |

| Start MN | Start | Actual End Date | End MN | Reclassified Equipment | Region | Reason | Source |
|-------------|--------------------|--------------------|-----------|--|--------|-----------|--------|
| 64651 | 29/09/2018 1845hrs | 29/09/2018 2150hrs | 64652 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 64670 | 30/09/2018 0640hrs | 30/09/2018 0945hrs | 64671 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 64673 | 30/09/2018 0920hrs | 30/09/2018 1325hrs | 64675 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 64672 | 30/09/2018 1020hrs | 30/09/2018 1225hrs | 64674 | Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | Lightning | INDJI |
| 64677 | 30/09/2018 1625hrs | 1/10/2018 1750hrs | 64695 | Chalumbin – Walkamin No.876 and Chalumbin – Woree No.877 275 kV lines | QLD | Bushfires | TNSP |
| 64719 | 5/10/2018 1620hrs | 5/10/2018 2325hrs | 64722 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 64720 | 5/10/2018 2100hrs | 5/10/2018 2200hrs | 64721 | Bouldercombe – Rockhampton No. 7108 and Bouldercombe – Egans Hill No. 7221 132 kV lines | QLD | Lightning | INDJI |
| 64723 | 6/10/2018 1245hrs | 6/10/2018 1545hrs | 64737 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 64739 | 7/10/2018 1410hrs | 7/10/2018 1615hrs | 64740 | Bouldercombe – Rockhampton No. 7108 and Bouldercombe – Egans Hill No. 7221 132 kV lines | QLD | Lightning | INDJI |
| 64741 | 7/10/2018 1625hrs | 7/10/2018 1930hrs | 64742 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 64756 | 8/10/2018 1245hrs | 8/10/2018 1650hrs | 64759 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 64757 | 8/10/2018 1425hrs | 8/10/2018 1525hrs | 64758 | Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | Lightning | INDJI |
| 64764 | 9/10/2018 1325hrs | 9/10/2018 1925hrs | 64770 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 64765 | 9/10/2018 1550hrs | 9/10/2018 1850hrs | 64767 | Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | Lightning | INDJI |
| 64768 | 9/10/2018 1905hrs | 9/10/2018 2105hrs | | Bouldercombe – Rockhampton No. 7108 and Bouldercombe – Egans Hill No. 7221 132 kV lines | QLD | Lightning | INDJI |
| 64773 | 10/10/2018 1325hrs | 10/10/2018 1630hrs | 64777 | Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | Lightning | INDJI |
| 64776 | 10/10/2018 1430hrs | 10/10/2018 1730hrs | 64778 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 64792 | 11/10/2018 0950hrs | 11/10/2018 1455hrs | 64797 | Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | Lightning | INDJI |
| 64793 | 11/10/2018 1010hrs | 11/10/2018 2010hrs | 64801 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 64798 | 11/10/2018 1525hrs | 11/10/2018 1825hrs | 64800 | Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | Lightning | INDJI |
| 64803 | 12/10/2018 0315hrs | 12/10/2018 0415hrs | 64804 | Goonyella – North Goonyella Tee – Stoney Creek No. 7122 and the Goonyella – Newlands No. 7155 132 kV lines | QLD | Lightning | INDJI |

| Start MN | Start | Actual End Date | End MN | Reclassified Equipment | Region | Reason | Source |
|-------------|--------------------|--------------------|-----------|--|--------|-----------|--------|
| 64805 | 12/10/2018 0645hrs | 12/10/2018 0650hrs | 64806 | Collinsville – Mackay tee Proserpine 7125 and 7126 132 kV lines | QLD | Lightning | INDJI |
| 64807 | 12/10/2018 0715hrs | 12/10/2018 0820hrs | 64808 | Goonyella – North Goonyella Tee – Stoney Creek No. 7122 and the Goonyella – Newlands No. 7155 132 kV lines | QLD | Lightning | INDJI |
| 64822 | 12/10/2018 1050hrs | 12/10/2018 1450hrs | 64833 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 64823 | 12/10/2018 1130hrs | 12/10/2018 1500hrs | 64834 | Moranbah Goonyella 7369 and 7370 132 kV lines | QLD | Lightning | INDJI |
| 64824 | 12/10/2018 1145hrs | 12/10/2018 1445hrs | 64832 | Goonyella – North Goonyella Tee – Stoney Creek No. 7122 and the Goonyella – Newlands No. 7155 132 kV lines | QLD | Lightning | INDJI |
| 64824 | 12/10/2018 1210hrs | 12/10/2018 1310hrs | 64828 | Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | Lightning | INDJI |
| 64830 | 12/10/2018 1405hrs | 12/10/2018 2335hrs | 64841 | 7306 Collinsville – Stony Ck and Collinsville – Newlands 132 kV lines | QLD | Lightning | INDJI |
| 64835 | 12/10/2018 1520hrs | 12/10/2018 2220hrs | 64839 | Goonyella – North Goonyella Tee – Stoney Creek No. 7122 and the Goonyella – Newlands No. 7155 132 kV lines | QLD | Lightning | INDJI |
| 64836 | 12/10/2018 1825hrs | 12/10/2018 2330hrs | 64840 | Collinsville – Mackay tee Proserpine 7125 and 7126 132 kV lines | QLD | Lightning | INDJI |
| 64837 | 12/10/2018 1845hrs | 13/10/2018 0045hrs | 64844 | Ross to Chalumbin 857 & 858 275 kV transmission lines | QLD | Lightning | INDJI |
| 64838 | 12/10/2018 2205hrs | 13/10/2018 0205hrs | 64846 | Chalumbin – Turkinjie No. 7165 and No. 7166 132 kV lines | QLD | Lightning | INDJI |
| 64842 | 13/10/2018 0010hrs | 13/10/2018 0210hrs | 64847 | Goonyella – North Goonyella Tee – Stoney Creek No. 7122 and the Goonyella – Newlands No. 7155 132 kV lines | QLD | Lightning | INDJI |
| 64843 | 13/10/2018 0035hrs | 13/10/2018 0225hrs | 64849 | Moranbah Goonyella 7369 and 7370 132 kV lines | QLD | Lightning | INDJI |
| 64845 | 13/10/2018 0110hrs | 13/10/2018 0210hrs | 64848 | 7306 Collinsville – Stony Ck and Collinsville – Newlands 132 kV lines | QLD | Lightning | INDJI |
| 64850 | 13/10/2018 0240hrs | 13/10/2018 0540hrs | 64853 | Bouldercombe – Rockhampton No. 7108 and Bouldercombe – Egans Hill No. 7221 132 kV lines | QLD | Lightning | INDJI |
| 64851 | 13/10/2018 0400hrs | 13/10/2018 0730hrs | 64856 | Ross to Chalumbin 857 & 858 275 kV transmission lines | QLD | Lightning | INDJI |
| 64858 | 13/10/2018 1105hrs | 13/10/2018 1910hrs | 64868 | Bouldercombe – Rockhampton No. 7108 and Bouldercombe – Egans Hill No. 7221 132 kV lines | QLD | Lightning | INDJI |
| 64859 | 13/10/2018 1230hrs | 13/10/2018 2100hrs | 64869 | Ross to Chalumbin 857 & 858 275 kV transmission lines | QLD | Lightning | INDJI |
| 64861 | 13/10/2018 1450hrs | 13/10/2018 1820hrs | 64867 | Chalumbin – Turkinjie No. 7165 and No. 7166 132 kV lines | QLD | Lightning | INDJI |
| 64864 | 13/10/2018 1535hrs | 13/10/2018 2135hrs | 64870 | Moranbah Goonyella 7369 and 7370 132 kV lines | QLD | Lightning | INDJI |

| Start MN | Start | Actual End Date | End MN | Reclassified Equipment | Region | Reason | Source |
|-------------|--------------------|--------------------|-----------|--|--------|-----------|--------|
| 64865 | 13/10/2018 1550hrs | 13/10/2018 2150hrs | 64871 | Goonyella – North Goonyella Tee – Stoney Creek No. 7122 and the Goonyella – Newlands No. 7155 132 kV lines | QLD | Lightning | INDJI |
| 64872 | 14/10/2018 0040hrs | 14/10/2018 0140hrs | 64874 | Bouldercombe – Rockhampton No. 7108 and Bouldercombe – Egans Hill No. 7221 132 kV lines | QLD | Lightning | INDJI |
| 64904 | 16/10/2018 1515hrs | 16/10/2018 1645hrs | 64907 | Ross to Chalumbin 857 & 858 275 kV transmission lines | QLD | Lightning | INDJI |
| 64906 | 16/10/2018 1640hrs | 16/10/2018 1755hrs | 64910 | Chalumbin – Turkinjie No. 7165 and No. 7166 132 kV lines | QLD | Lightning | INDJI |
| 64908 | 16/10/2018 1655hrs | 16/10/2018 1855hrs | 64911 | Ross to Chalumbin 857 & 858 275 kV transmission lines | QLD | Lightning | INDJI |
| 64912 | 16/10/2018 1920hrs | 16/10/2018 2025hrs | 64914 | Chalumbin – Turkinjie No. 7165 and No. 7166 132 kV lines | QLD | Lightning | INDJI |
| 64918 | 17/10/2018 1220hrs | 17/10/2018 1220hrs | 64920 | Collinsville – Mackay tee Proserpine 7125 and 7126 132 kV lines | QLD | Lightning | INDJI |
| 64919 | 17/10/2018 1220hrs | 17/10/2018 2220hrs | 64944 | 7306 Collinsville – Stony Ck and Collinsville – Newlands 132 kV lines | QLD | Lightning | INDJI |
| 64921 | 17/10/2018 1225hrs | 17/10/2018 1755hrs | 64942 | Goonyella – North Goonyella Tee – Stoney Creek No. 7122 and the Goonyella – Newlands No. 7155 132 kV lines | QLD | Lightning | INDJI |
| 64922 | 17/10/2018 1300hrs | 17/10/2018 2230hrs | 64945 | Moranbah Goonyella 7369 and 7370 132 kV lines | QLD | Lightning | INDJI |
| 64938 | 17/10/2018 1450hrs | 17/10/2018 1720hrs | 64940 | Ross to Chalumbin 857 & 858 275 kV transmission lines | QLD | Lightning | INDJI |
| 64943 | 17/10/2018 2030hrs | 17/10/2018 2335hrs | 64947 | Ross to Chalumbin 857 & 858 275 kV transmission lines | QLD | Lightning | INDJI |
| 64948 | 18/10/2018 0110hrs | 18/10/2018 0510hrs | 64953 | Ross to Chalumbin 857 & 858 275 kV transmission lines | QLD | Lightning | INDJI |
| 64949 | 18/10/2018 0145hrs | 18/10/2018 0345hrs | 64951 | Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | Lightning | INDJI |
| 64976 | 18/10/2018 1420hrs | 18/10/2018 1520hrs | 64978 | Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | Lightning | INDJI |
| 64977 | 18/10/2018 1455hrs | 18/10/2018 1555hrs | 64981 | 7306 Collinsville – Stony Ck and Collinsville – Newlands 132 kV lines | QLD | Lightning | INDJI |
| 64979 | 18/10/2018 1535hrs | 18/10/2018 2135hrs | 65011 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 64980 | 18/10/2018 1540hrs | 18/10/2018 1640hrs | 64984 | Ross to Chalumbin 857 & 858 275 kV transmission lines | QLD | Lightning | INDJI |
| 64982 | 18/10/2018 1610hrs | 18/10/2018 1810hrs | 65003 | Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | Lightning | INDJI |
| 64985 | 18/10/2018 1650hrs | 18/10/2018 1820hrs | 65004 | Ross to Chalumbin 857 & 858 275 kV transmission lines | QLD | Lightning | INDJI |
| 65012 | 19/10/2018 0020hrs | 19/10/2018 0325hrs | 65014 | Chalumbin – Turkinjie No. 7165 and No. 7166 132 kV lines | QLD | Lightning | INDJI |
| 55057 | 20/10/2018 2040hrs | 21/11/2018 0045hrs | 65060 | Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | Lightning | INDJI |

| Start MN | Start | Actual End Date | End MN | Reclassified Equipment | Region | Reason | Source |
|-------------|--------------------|--------------------|-----------|--|--------|-----------|--------|
| 65059 | 20/10/2018 2150hrs | 21/10/2018 0050hrs | 65061 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 65062 | 21/10/2018 0425hrs | 21/10/2018 1230hrs | 65070 | Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | Lightning | INDJI |
| 65063 | 21/10/2018 0425hrs | 21/10/2018 0700hrs | 65064 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 65066 | 21/10/2018 0740hrs | 21/10/2018 1645hrs | 65075 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 65073 | 21/10/2018 1420hrs | 21/10/2018 1625hrs | 65074 | Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | Lightning | INDJI |
| 65081 | 22/10/2018 1835hrs | 22/10/2018 2310hrs | 65086 | Goonyella – North Goonyella Tee – Stoney Creek No. 7122 and the Goonyella – Newlands No. 7155 132 kV lines | QLD | Lightning | INDJI |
| 65083 | 22/10/2018 1935hrs | 22/10/2018 2310hrs | 65087 | Moranbah Goonyella 7369 and 7370 132 kV lines | QLD | Lightning | INDJI |
| 65084 | 22/10/2018 1950hrs | 22/10/2018 2250hrs | 65085 | Bouldercombe – Rockhampton No. 7108 and Bouldercombe – Egans Hill No. 7221 132 kV lines | QLD | Lightning | INDJI |
| 65088 | 23/10/2018 0310hrs | 23/10/2018 0410hrs | 65090 | 7306 Collinsville – Stony Ck and Collinsville – Newlands 132 kV lines | QLD | Lightning | INDJI |
| 65097 | 23/10/2018 1520hrs | 23/10/2018 1720hrs | 65102 | Ross to Chalumbin 857 & 858 275 kV transmission lines | QLD | Lightning | INDJI |
| 65098 | 23/10/2018 1540hrs | 23/10/2018 1740hrs | 65105 | 7306 Collinsville – Stony Ck and Collinsville – Newlands 132 kV lines | QLD | Lightning | INDJI |
| 65099 | 23/10/2018 1550hrs | 23/10/2018 1655hrs | 65101 | Goonyella – North Goonyella Tee – Stoney Creek No. 7122 and the Goonyella – Newlands No. 7155 132 kV lines | QLD | Lightning | INDJI |
| 65100 | 23/10/2018 1645hrs | 23/10/2018 1750hrs | 65106 | Collinsville – Mackay tee Proserpine 7125 and 7126 132 kV lines | QLD | Lightning | INDJI |
| 65119 | 24/10/2018 2100hrs | 24/10/2018 2200hrs | 65120 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 65123 | 25/10/2018 1655hrs | 26/10/2018 0600hrs | 65128 | Ross to Chalumbin 857 & 858 275 kV transmission lines | QLD | Bushfires | INDJI |
| 65125 | 25/10/2018 1855hrs | 25/10/2018 2155hrs | 65127 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 65129 | 26/10/2018 1640hrs | 27/10/2018 1320hrs | 65132 | Ross to Chalumbin 857 & 858 275 kV transmission lines | QLD | Bushfires | INDJI |
| 65133 | 28/10/2018 2205hrs | 28/10/2018 0110hrs | 65134 | Bouldercombe – Rockhampton No. 7108 and Bouldercombe – Egans Hill No. 7221 132 kV lines | QLD | Lightning | INDJI |
| 65138 | 29/10/2018 1615hrs | 29/10/2018 2020hrs | 65141 | Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | Lightning | INDJI |
| 65139 | 29/10/2018 1830hrs | 29/10/2018 2030hrs | 65142 | Goonyella – North Goonyella Tee – Stoney Creek No. 7122 and the Goonyella – Newlands No. 7155 132 kV lines | QLD | Lightning | INDJI |
| 65140 | 29/10/2018 1855hrs | 29/10/2018 2155hrs | 65143 | Bouldercombe – Rockhampton No. 7108 and Bouldercombe – Egans Hill No. 7221 132 kV lines | QLD | Lightning | INDJI |

| Start MN | Start | Actual End Date | End MN | Reclassified Equipment | Region | Reason | Source |
|-------------|--------------------|--------------------|-----------|--|--------|-----------|-------------------|
| 65146 | 30/10/2018 1610hrs | 30/10/2018 2215hrs | 65150 | Moranbah Goonyella 7369 and 7370 132 kV lines | QLD | Lightning | INDJI |
| 65147 | 30/10/2018 1610hrs | 30/10/2018 2215hrs | 65149 | Goonyella – North Goonyella Tee – Stoney Creek No. 7122 and the Goonyella – Newlands No. 7155 132 kV lines | QLD | Lightning | INDJI |
| 65151 | 30/10/2018 2320hrs | 31/10/2018 0220hrs | 65153 | Moranbah Goonyella 7369 and 7370 132 kV lines | QLD | Lightning | INDJI |
| 65152 | 30/10/2018 2320hrs | 31/10/2018 0230hrs | 65154 | Goonyella – North Goonyella Tee – Stoney Creek No. 7122 and the Goonyella – Newlands No. 7155 132 kV lines | QLD | Lightning | INDJI |
| 65155 | 31/10/2018 0540hrs | 31/10/2018 0745hrs | 65170 | Goonyella – North Goonyella Tee – Stoney Creek No. 7122 and the Goonyella – Newlands No. 7155 132 kV lines | QLD | Lightning | INDJI |
| 65156 | 31/10/2018 0540hrs | 31/10/2018 0745hrs | 65169 | Moranbah Goonyella 7369 and 7370 132 kV lines | QLD | Lightning | INDJI |
| 65195 | 31/10/2018 1315hrs | 31/10/2018 1620hrs | 65197 | Bouldercombe – Rockhampton No. 7108 and Bouldercombe – Egans Hill No. 7221 132 kV lines | QLD | Lightning | INDJI |
| 65199 | 31/10/2018 1715hrs | 31/10/2018 1920hrs | 65202 | 7306 Collinsville – Stony Ck and Collinsville – Newlands 132 kV lines | QLD | Lightning | INDJI |
| 65200 | 31/10/2018 1715hrs | 31/10/2018 2150hrs | 65217 | Goonyella – North Goonyella Tee – Stoney Creek No. 7122 and the Goonyella – Newlands No. 7155 132 kV lines | QLD | Lightning | INDJI |
| 65203 | 31/10/2018 1940 | 31/10/2018 2145hrs | 65216 | Moranbah Goonyella 7369 and 7370 132 kV lines | QLD | Lightning | INDJI |
| 62656 | 2/05/2018 1720hrs | 3/05/2018 1700hrs | 62695 | Brinkworth – Templers West and Para – Templers West 275 kV lines | SA | Other | ВОМ |
| 62657 | 2/05/2018 1720hrs | 4/06/2018 0530hrs | 62702 | Para – Templers West and TIPS A – Magill 275 kV lines | SA | Other | ВОМ |
| 62696 | 4/05/2018 0055hrs | 4/05/2018 0525hrs | 62701 | Brinkworth – Templers West and Para – Templers West 275 kV lines | SA | Other | ВОМ |
| 62780 | 10/05/2018 0825hrs | 11/05/2018 0045hrs | 62797 | Para – Templers West and TIPS A – Magill 275 kV lines | SA | Other | ВОМ |
| 62916 | 23/05/2018 1530hrs | 27/05/2018 1115hrs | 62953 | Loss of Pelican Point GT 12 with any other generating unit | SA | Lightning | Event Occurred |
| 62972 | 28/05/2018 1440hrs | 29/05/2018 0540hrs | 63008 | Brinkworth – Templers West and Para – Templers West 275 kV lines | SA | Other | ВОМ |
| 62976 | 28/05/2018 2020hrs | 28/05/2018 2355hrs | 62979 | Brinkworth – Davenport, Brinkworth – Templers West and Para – Templers West 275 kV lines | SA | Other | ВОМ |
| 63178 | 11/06/2018 1805hrs | 11/06/2018 2335hrs | 63180 | Brinkworth – Davenport, Brinkworth – Templers West and Para – Templers West 275 kV lines | SA | Other | ВОМ |
| 63179 | 11/06/2018 1805hrs | 12/06/2018 0315hrs | 63181 | Para – Templers West and TIPS A – Magill 275 kV lines | SA | Other | ВОМ |

| Start MN | Start | Actual End Date | End MN | Reclassified Equipment | Region | Reason | Source |
|-------------|--------------------|--------------------|-----------|--|--------|-----------|----------------------------------|
| 63189 | 13/06/2018 1715hrs | 13/06/2018 1805hrs | 63192 | Brinkworth – Davenport, Brinkworth – Templers West and Para – Templers West 275 kV lines | SA | Other | ВОМ |
| 63190 | 13/06/2018 1720hrs | 13/06/2018 1805hrs | 63193 | Para – Templers West and TIPS A – Magill 275 kV lines | SA | Other | ВОМ |
| 63202 | 14/06/2018 0705hrs | 14/06/2018 2040hrs | 63214 | Brinkworth – Davenport, Brinkworth – Templers West and Para – Templers West 275 kV lines | SA | Lightning | ВОМ |
| 63203 | 14/06/2018 0705hrs | 14/06/2018 2040hrs | 63215 | Para – Templers West and TIPS A – Magill 275 kV lines | SA | Other | BOM |
| 63236 | 16/06/2018 1610hrs | 16/06/2018 2010hrs | 63238 | Brinkworth – Davenport, Brinkworth – Templers West and Para – Templers West 275 kV lines | SA | Other | ВОМ |
| 63237 | 16/06/2018 1610hrs | 16/06/2018 2010hrs | 63239 | Para – Templers West and Magill – Torrens Island A 275 kV lines | SA | Other | BOM |
| 63258 | 22/06/2018 0935hrs | 29/06/2018 1540hrs | 63290 | Loss of Pelican Point GT 11 with any other generating unit | SA | Other | Event Occurred |
| 63344 | 4/07/2018 0135hrs | 4/07/2018 0820hrs | 63348 | Para – Templers West and Magill – Torrens Island A 275 kV lines | SA | Other | BOM Severe Weather warning |
| 63367 | 5/07/2018 1450hrs | 6/07/2018 1155hrs | 63378 | Para – Templers West and Magill – Torrens Island A 275 kV lines | SA | Other | BOM severe weather warning |
| 63390 | 6/07/2018 1920hrs | 7/07/2018 1230hrs | 63399 | Para –Templers West and the Magill – Torrens Island A 275 kV lines | SA | Other | BOM severe weather warning |
| 63391 | 6/07/2018 1920hrs | 7/07/2018 1040hrs | 63398 | Brinkworth – Davenport, Brinkworth – Templers West and Para – Templers West 275 kV lines | SA | Other | BOM severe weather warning |
| 63487 | 17/07/2018 0155hrs | 17/07/2018 1730hrs | 63500 | Para –Templers West and the Magill – Torrens Island A 275 kV lines | SA | Other | BOM severe weather warning |
| 63488 | 17/07/2018 0210hrs | 17/07/2018 1730hrs | 63499 | Brinkworth – Davenport, Brinkworth – Templers West and Para – Templers West 275 kV lines | SA | Other | BOM severe weather warning |
| 63565 | 23/07/2018 1145hrs | 24/07/2018 0545hrs | 63578 | Para – Templers West and Magill – Torrens Island A 275 kV lines | SA | Other | BOM severe weather warning |

| Start MN | Start | Actual End Date | End MN | Reclassified Equipment | Region | Reason | Source |
|-------------|--------------------|--------------------|-----------|---|--------|--------|----------------------------------|
| 63566 | 23/07/2018 1145hrs | 24/07/2018 0545hrs | 63577 | Brinkworth – Davenport, Brinkworth – Templers West and Para – Templers West 275 kV lines | SA | Other | BOM severe weather warning |
| 63579 | 24/07/2018 0740hrs | 24/07/2018 1655hrs | 63584 | Para – Templers West and Magill – Torrens Island A 275 kV lines | SA | Other | BOM severe weather warning |
| 63649 | 30/07/2018 1540hrs | 31/07/2018 0005hrs | 63657 | Para – Templers West and Magill – Torrens Island A 275 kV lines | SA | Other | BOM severe weather warning |
| 63698 | 1/08/2018 2350hrs | 10/08/2018 1530hrs | 63835 | Trip of Mount Gambier No.2 132/33 kV transformer due to a fault on the local 132 kV network | SA | Other | Event Occurred |
| 63701 | 2/08/2018 0720hrs | 2/08/2018 1735hrs | 63705 | Para – Templers West and Magill – Torrens Island A 275 kV lines | SA | Other | BOM severe weather warning |
| 63702 | 2/08/2018 0725hrs | 2/08/2018 1735hrs | 63706 | Brinkworth – Davenport, Brinkworth – Templers West and Para – Templers West 275 kV lines | SA | Other | BOM severe weather warning |
| 63786 | 7/08/2018 1820hrs | 8/08/2018 0555hrs | 63791 | Para – Templers West and Magill – Torrens Island A 275 kV lines | SA | Other | BOM severe weather warning |
| 63822 | 9/08/2018 1800hrs | 10/08/2018 1625hrs | 63836 | Brinkworth – Davenport, Brinkworth – Templers West and Para – Templers West 275 kV lines | SA | Other | BOM severe weather warning |
| 63823 | 9/08/2018 1800hrs | 10/08/2018 1625hrs | 63837 | Para – Templers West and Magill – Torrens Island A 275 kV lines | SA | Other | BOM severe weather warning |
| 63882 | 14/08/2018 2340hrs | 15/08/2018 1100hrs | 63912 | Para – Templers West and Magill – Torrens Island A 275 kV lines | SA | Other | BOM severe weather warning |
| 63943 | 18/08/2018 0540hrs | 18/08/2018 1110hrs | 63944 | Para – Templers West and Magill – Torrens Island A 275 kV lines | SA | Other | BOM severe weather warning |
| 63973 | 22/08/2018 0920hrs | 22/08/2018 1700hrs | 63978 | South East No. 2 275/132 kV Transformer and both the South East No.1 and No.2 275 kV SVCs | SA | Other | TNSP |

| Start MN | Start | Actual End Date | End MN | Reclassified Equipment | Region | Reason | Source |
|-------------|--------------------|--------------------|-----------|--|--------|-----------|----------------------------------|
| 64045 | 30/08/2018 1300hrs | 30/08/2018 1440hrs | 64047 | Brinkworth – Davenport, Brinkworth – Templers West and Para – Templers West 275 kV lines | SA | Other | BOM severe weather warning |
| 64046 | 30/08/2018 1300hrs | 30/08/2018 1440hrs | 64048 | Para – Templers West and Magill – Torrens Island A 275 kV lines | SA | Other | BOM severe weather warning |
| 64176 | 11/09/2018 0540hrs | 11/09/2018 1850hrs | 64184 | Brinkworth – Davenport, Brinkworth – Templers West and Para – Templers West 275 kV lines | SA | Other | BOM severe weather warning |
| 64175 | 11/09/2018 0545hrs | 11/09/2018 1850hrs | 64183 | Para – Templers West and Magill – Torrens Island A 275 kV lines | SA | Other | BOM severe weather warning |
| 64223 | 14/09/2018 1655hrs | 15/09/2018 1810hrs | 64242 | Brinkworth – Davenport, Brinkworth – Templers West and Para – Templers West 275 kV lines | SA | Other | BOM severe weather warning |
| 64224 | 14/09/2018 1655hrs | 15/09/2018 1810hrs | 64243 | Para – Templers West and Magill – Torrens Island A 275 kV lines | SA | Other | BOM severe weather warning |
| 64877 | 14/10/2018 1640hrs | 14/10/2018 1800hrs | 64878 | Brinkworth – Davenport, Brinkworth – Templers West and Para – Templers West 275 kV lines | SA | Other | ВОМ |
| 64891 | 14/10/2018 2305hrs | 15/10/2018 1450hrs | 64901 | Brinkworth – Davenport, Brinkworth – Templers West and Para – Templers West 275 kV lines | SA | Other | ВОМ |
| 64892 | 14/10/2018 2305hrs | 15/10/2018 1450hrs | 64902 | Para – Templers West and Magill – Torrens Island A 275 kV lines | SA | Other | ВОМ |
| 65015 | 19/10/2018 0705hrs | 19/10/2018 1250hrs | 65034 | Brinkworth – Davenport, Brinkworth – Templers West and Para – Templers West 275 kV lines | SA | Other | ВОМ |
| 65017 | 19/10/2018 1250hrs | 19/10/2018 1750hrs | 65035 | Para – Templers West and Magill – Torrens Island A 275 kV lines | SA | Other | BOM |
| 62703 | 4/05/2018 0555hrs | 4/05/2018 0730hrs | 62704 | Farrell Reece No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 62713 | 4/05/2018 2100hrs | 4/05/2018 2205hrs | 62714 | Farrell Reece No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 62793 | 10/05/2018 2010hrs | 11/05/2018 0110hrs | 62798 | Chapel St – Liapootah No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 62794 | 10/05/2018 2135hrs | 11/05/2018 0035hrs | 62795 | Tungatinah – New Norfolk tee Meadowbank No. 1 and No. 2 110 kV lines | TAS | Lightning | INDJI |
| 62799 | 11/05/2018 0240hrs | 11/05/2018 0445hrs | 62802 | Chapel St – Liapootah No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |

| Start MN | Start | Actual End Date | End MN | Reclassified Equipment | Region | Reason | Source |
|-------------|--------------------|--------------------|-----------|---|--------|-----------|--------|
| 62800 | 11/05/2018 0240hrs | 11/06/2018 0445hrs | 62801 | Tungatinah – New Norfolk tee Meadowbank No. 1 and No. 2 110 kV lines | | Lightning | INDJI |
| 62803 | 11/05/2018 0545hrs | 11/05/2018 0645hrs | 62804 | Norwood–Scottsdale–Derby 110 kV line and Norwood–Scottsdale 110 kV line | TAS | Lightning | INDJI |
| 63025 | 30/05/2018 1535hrs | 30/05/2018 1640hrs | 63043 | Farrell – Sheffield No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 63031 | 30/05/2018 1600hrs | 30/05/2018 1830hrs | 63044 | Norwood – Scottsdale – Derby 110 kV line and Norwood – Scottsdale 110 kV line | TAS | Lightning | INDJI |
| 63216 | 14/06/2018 2145hrs | 15/06/2018 0225hrs | 63217 | Farrell – Sheffield No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 63218 | 15/06/2018 0225hrs | 15/06/2018 0325hrs | 63219 | Norwood – Scottsdale – Derby 110 kV line and Norwood – Scottsdale 110 kV line | TAS | Lightning | INDJI |
| 63369 | 6/07/2018 0020hrs | 6/07/2018 0125hrs | 63371 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | ILDNI |
| 63370 | 6/07/2018 0020hrs | 6/08/2018 0125hrs | 63372 | Farrell Reece No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 63373 | 6/07/2018 0600hrs | 6/07/2018 0700hrs | 63375 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | ILDNI |
| 63374 | 6/07/2018 0605hrs | 6/07/2018 0805hrs | 63376 | Norwood–Scottsdale–Derby 110 kV line and Norwood–Scottsdale 110 kV line | TAS | Lightning | INDJI |
| 63377 | 6/07/2018 1100hrs | 6/07/2018 1205hrs | 63380 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | INDJI |
| 63386 | 6/07/2018 1435hrs | 6/07/2018 1540hrs | 63388 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | INDJI |
| 63392 | 7/07/2018 0340hrs | 7/07/2018 0445hrs | 63393 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | INDJI |
| 63498 | 17/07/2018 1635hrs | 17/07/2018 1740hrs | 63501 | Norwood – Scottsdale – Derby 110 kV line and Norwood – Scottsdale 110 kV line | TAS | Lightning | INDJI |
| 63503 | 18/07/2018 0140hrs | 18/07/2018 0210hrs | 63504 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | INDJI |
| 63515 | 18/07/2018 1730hrs | 18/07/2018 1935hrs | 63516 | Farrell Reece No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 63517 | 19/07/2018 0035hrs | 19/07/2018 0335hrs | 63520 | Farrell Reece No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 63518 | 19/07/2018 0125hrs | 19/07/2018 0325hrs | 63519 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | | Lightning | INDJI |
| 63523 | 19/07/2018 1105hrs | 19/07/2018 1205hrs | 63524 | Farrell Reece No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 63526 | 19/07/2018 1420hrs | 19/07/2018 1620hrs | 63530 | Farrell – Sheffield No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |

| Start MN | Start | Actual End Date | End MN | Reclassified Equipment | Region | Reason | Source |
|-------------|--------------------|--------------------|-----------|---|--------|-----------|--------|
| 63527 | 19/07/2018 1425hrs | 19/07/2018 1620hrs | 63529 | Farrell Reece No. 1 and No. 2 220 kV lines | | Lightning | INDJI |
| 63528 | 19/07/2018 1425hrs | 19/07/2018 1620hrs | 63531 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | INDJI |
| 63542 | 20/07/2018 0730hrs | 20/07/2018 0830hrs | 63543 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | INDJI |
| 63581 | 24/07/2018 1405hrs | 24/07/2018 1505hrs | 63582 | Farrell Reece No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 63583 | 24/07/2018 1625hrs | 24/07/2018 1725hrs | 63585 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | INDJI |
| 63586 | 24/07/2018 1735hrs | 24/07/2018 1835hrs | 63587 | Farrell Reece No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 63588 | 24/07/2018 1855hrs | 24/07/2018 2055hrs | 63590 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | INDJI |
| 63677 | 31/07/2018 1340hrs | 31/07/2018 1505hrs | 63679 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | INDJI |
| 63680 | 31/07/2018 1540hrs | 31/07/2018 1650hrs | 63684 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | INDJI |
| 63681 | 31/07/2018 1540hrs | 31/07/2018 1645hrs | 63683 | Farrell Reece No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 63682 | 31/07/2018 1550hrs | 31/07/2018 1655hrs | 63685 | Farrell – Sheffield No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 63761 | 6/08/2018 0610hrs | 6/08/2018 0915hrs | 63765 | Norwood – Scottsdale – Derby 110 kV line and Norwood – Scottsdale 110 kV line | TAS | Lightning | INDJI |
| 63885 | 15/08/2018 0520hrs | 15/08/2018 0620hrs | 63887 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | INDJI |
| 63888 | 15/08/2018 0630hrs | 15/08/2018 1030hrs | 63910 | Farrell Reece No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 63889 | 15/08/2018 0645hrs | 15/08/2018 0845hrs | 63894 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | INDJI |
| 53895 | 15/08/2018 0920hrs | 15/08/2018 1220hrs | 69316 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | INDJI |
| 63896 | 15/08/2018 0920hrs | 15/08/2018 1150hrs | 63914 | Farrell – Sheffield No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 63909 | 15/08/2018 1010hrs | 15/08/2018 1210hrs | 63915 | Norwood – Scottsdale – Derby 110 kV line and Norwood – Scottsdale 110 kV line | TAS | Lightning | INDJI |
| 53917 | 15/08/2018 1040hrs | 15/08/2018 1140hrs | 63913 | Farrell Reece No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |

| Start MN | Start | Actual End Date | End MN | Reclassified Equipment | Region | Reason | Source |
|-------------|--------------------|--------------------|-----------|---|--------|-----------|-------------------|
| 63917 | 15/08/2018 1335hrs | 15/08/2018 2105hrs | 63924 | Farrell – Sheffield No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 63918 | 15/08/2018 1335hrs | 15/08/2018 2035hrs | 63922 | Farrell Reece No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 63919 | 15/08/2018 1335hrs | 15/08/2018 2055hrs | 63922 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | INDJI |
| 63941 | 18/08/2018 0350hrs | 18/08/2018 0450hrs | 63942 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | INDJI |
| 64186 | 11/09/2018 2100hrs | 11/09/2018 2200hrs | 64187 | Farrell Reece No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 64226 | 15/09/2018 0250hrs | 15/09/2018 0345hrs | 64231 | Farrell Reece No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 64227 | 15/09/2018 0250hrs | 15/09/2018 0345hrs | 64232 | Farrell – Sheffield No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 64228 | 15/09/2018 0250hrs | 15/09/2018 0345hrs | 64233 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | INDJI |
| 64238 | 15/09/2018 1630hrs | 15/09/2018 1900hrs | 64246 | Farrell Reece No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 64239 | 15/09/2018 1630hrs | 15/09/2018 1900hrs | 64247 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | INDJI |
| 64240 | 15/09/2018 1630hrs | 15/09/2018 1900hrs | 64248 | Farrell – Sheffield No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 64289 | 18/09/2018 1200hrs | 18/09/2018 1405hrs | 64296 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | INDJI |
| 64290 | 18/09/2018 1200hrs | 18/09/2018 1305hrs | 64293 | Farrell Reece No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 64304 | 19/09/2018 1430hrs | 19/09/2018 1630hrs | 64308 | Norwood – Scottsdale – Derby 110 kV line and Norwood – Scottsdale 110 kV line | TAS | Lightning | INDJI |
| 64967 | 18/10/2018 1220hrs | 18/10/2018 1320hrs | 64973 | Farrell Reece No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 64968 | 18/10/2018 1220hrs | 18/10/2018 1320hrs | 64974 | Farrell – Sheffield No. 1 and No. 2 220 kV lines | TAS | Lightning | INDJI |
| 64969 | 18/10/2018 1225hrs | 18/10/2018 1320hrs | 64975 | Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | Lightning | INDJI |
| 62995 | 29/05/2018 0300hrs | 3/06/2018 1745hrs | 63057 | Rowville to Templestowe 220 kV line at the Templestowe end only | VIC | Other | Event Occurred |
| 63009 | 29/05/2018 1015hrs | 29/05/2018 1115hrs | 63013 | Glenrowan – Dederang No. 1 and No. 3 220 kV lines | VIC | Lightning | INDJI |
| 63201 | 14/06/2018 0320hrs | 19/06/2018 1450hrs | 63247 | Loss of Alcoa Portland (APD) Potline 1 and Potline 2 | VIC | Other | Event Occurred |

| Start MN | Start | Actual End Date | End MN | Reclassified Equipment | Region | Reason | Source |
|-------------|--------------------|--------------------|-----------|---|--------|-----------|--------|
| 63532 | 19/07/2018 1800hrs | 19/07/2018 1900hrs | 63533 | Eildon – Mt Beauty No. 1 and No. 2 220 kV lines | | Lightning | INDJI |
| 63535 | 19/07/2018 2120hrs | 20/07/2018 0020hrs | 63537 | Eildon – Mt Beauty No. 1 and No. 2 220 kV lines | VIC | Lightning | INDJI |
| 63538 | 20/07/2018 0055hrs | 20/07/2018 0255hrs | 63540 | Eildon – Mt Beauty No. 1 and No. 2 220 kV lines | VIC | Lightning | INDJI |
| 63539 | 20/07/2018 0055hrs | 20/07/2018 0255hrs | 63541 | Glenrowan – Dederang No. 1 and No. 3 220 kV lines | VIC | Lightning | INDJI |
| 63847 | 11/08/2018 1710hrs | 11/08/2018 2015hrs | 63853 | Glenrowan – Dederang No. 1 and No. 3 220 kV lines | VIC | Lightning | INDJI |
| 63848 | 11/08/2018 1800hrs | 11/08/2018 1900hrs | 63852 | Eildon – Mt Beauty No. 1 and No. 2 220 kV lines | VIC | Lightning | INDJI |
| 63854 | 11/08/2018 2120hrs | 11/08/2018 2220hrs | 63856 | Eildon – Mt Beauty No. 1 and No. 2 220 kV lines | VIC | Lightning | INDJI |
| 63855 | 11/08/2018 2120hrs | 11/08/2018 2220hrs | 63857 | Glenrowan – Dederang No. 1 and No. 3 220 kV lines | VIC | Lightning | INDJI |
| 63946 | 18/08/2018 1510hrs | 18/08/2018 1945hrs | 63949 | Eildon – Mt Beauty No. 1 and No. 2 220 kV lines | VIC | Lightning | INDJI |
| 63948 | 18/08/2018 1745hrs | 18/08/2018 1945hrs | 63950 | Glenrowan – Dederang No. 1 and No. 3 220 kV lines | VIC | Lightning | INDJI |
| 64104 | 6/09/2018 1610hrs | 6/09/2018 2010hrs | 64109 | Glenrowan – Dederang No. 1 and No. 3 220 kV lines | VIC | Lightning | INDJI |
| 64106 | 6/09/2018 1740hrs | 6/09/2018 1910hrs | 64108 | Eildon – Mt Beauty No. 1 and No. 2 220 kV lines | VIC | Lightning | INDJI |
| 64110 | 6/09/2018 2110hrs | 6/09/2018 2210hrs | 64112 | Eildon – Mt Beauty No. 1 and No. 2 220 kV lines | VIC | Lightning | INDJI |
| 64111 | 6/09/2018 2110hrs | 6/09/2018 2210hrs | 64113 | Glenrowan – Dederang No. 1 and No. 3 220 kV lines | VIC | Lightning | INDJI |
| 64114 | 7/09/2018 0005hrs | 7/09/2018 0110hrs | 64115 | Eildon – Mt Beauty No. 1 and No. 2 220 kV lines | VIC | Lightning | INDJI |
| 64116 | 7/09/2018 0320hrs | 7/09/2018 0420hrs | 64117 | Eildon – Mt Beauty No. 1 and No. 2 220 kV lines | VIC | Lightning | INDJI |
| 64235 | 15/09/2018 1405hrs | 15/09/2018 1510hrs | 64237 | Eildon – Mt Beauty No. 1 and No. 2 220 kV lines | VIC | Lightning | INDJI |
| 64710 | 4/10/2018 1700hrs | 4/10/2018 1800hrs | 64711 | Glenrowan – Dederang No. 1 and No. 3 220 kV lines | VIC | Lightning | INDJI |
| 64936 | 17/10/2018 1430hrs | 17/10/2018 1535hrs | 64939 | Eildon – Mt Beauty No. 1 and No. 2 220 kV lines | VIC | Lightning | INDJI |
| 65036 | 20/10/2018 0835hrs | 20/10/2018 1035hrs | 65038 | Glenrowan – Dederang No. 1 and No. 3 220 kV lines | VIC | Lightning | INDJI |
| 65037 | 20/10/2018 0910hrs | 20/11/2018 1110hrs | 65039 | Eildon – Mt Beauty No. 1 and No. 2 220 kV lines | VIC | Lightning | INDJI |
| 65040 | 20/10/2018 1145hrs | 20/11/2018 1345hrs | 65042 | Glenrowan – Dederang No. 1 and No. 3 220 kV lines | VIC | Lightning | INDJI |
| 65041 | 20/10/2018 1150hrs | 20/11/2018 1350hrs | 65043 | Eildon – Mt Beauty No. 1 and No. 2 220 kV lines | VIC | Lightning | INDJI |

A2. Number of reclassification events on each element, 1 May 2018 to 31 October 2018

Table 3 Number of times reclassification events occurred on each element, 1 May 2018 to 31 October 2018

| Element | Region | Number of times reclassified | | | | | |
|---|---------|------------------------------|-----------|-------|-------|--|--|
| | | Bushfires | Lightning | Other | Total | | |
| Coffs Harbour to Lismore (89) 330 kV line and the Koolkhan to Lismore (967) 132 k V line | NSW | 1 | | | 1 | | |
| Bulli Creek – Dumaresq 8L and 8M 330 kV line | NSW/QLD | | 23 | 1 | 24 | | |
| 7306 Collinsville – Stony Ck and Collinsville – Newlands 132 kV lines | QLD | | 7 | | 7 | | |
| Bouldercombe – Rockhampton No. 7108 and Bouldercombe – Egans Hill No. 7221 132 kV lines | QLD | | 14 | | 14 | | |
| Chalumbin – Turkinjie No. 7165 and No. 7166 132 kV lines | QLD | | 5 | | 5 | | |
| Chalumbin – Walkamin No.876 and Chalumbin – Woree No.877 275 kV lines | QLD | 1 | | | 1 | | |
| Chinchilla – Columboola No. 7349 and No. 7350 132 kV lines | QLD | | 20 | | 20 | | |
| Collinsville – Mackay tee Proserpine 7125 and 7126 132 kV lines | QLD | | 4 | | 4 | | |
| Goonyella – North Goonyella Tee – Stoney Creek No. 7122 and the Goonyella – Newlands No. 7155 132 kV lines | QLD | | 14 | | 14 | | |
| Moranbah Goonyella 7369 and 7370 132 kV lines | QLD | | 10 | | 10 | | |
| Ross to Chalumbin 857 & 858 275 kV transmission lines | QLD | 4 | 11 | | 15 | | |
| Tarong – Chincilla 7183 and 7168 132 kV lines | QLD | | 30 | | 30 | | |
| Trip of Unit 3 Stanwell Power station and any one of the individual 275 kV transmission lines connected to H29 Stanwell | QLD | | | 1 | 1 | | |
| Trip of Strathmore No.1 and No. 2 132 kV buses | QLD | | | 1 | 1 | | |

| Element | Region | Number of times reclassified | | | |
|---|--------|------------------------------|-----------|-------|-------|
| | | Bushfires | Lightning | Other | Total |
| Brinkworth – Templers West and Para –Templers West 275 kV lines | SA | | | 3 | 3 |
| Brinkworth–Davenport, Brinkworth–Templers West and Para–Templers West 275 kV lines | SA | | 1 | 15 | 16 |
| Loss of Pelican Point GT 11 with any other generating unit | SA | | | 1 | 1 |
| Loss of Pelican Point GT 12 with any other generating unit | SA | | | 1 | 1 |
| Para – Templers West and TIPS A – Magill 275 kV lines | SA | | | 5 | 5 |
| Para –Templers West and the Magill – Torrens Island A 275 kV lines | SA | | | 2 | 2 |
| Para–Templers West and Magill–Torrens Island A 275 kV lines | SA | | | 16 | 16 |
| South East No. 2 275/132 kV Transformer and both the South East No.1 and No.2 275 kV SVCs | SA | | | 1 | 1 |
| Trip of Mount Gambier No.2 132/33 kV transformer due to a fault on the local 132 kV network | SA | | | 1 | 1 |
| Chapel St – Liapootah No. 1 and No. 2 220 kV lines | TAS | | 2 | | 2 |
| Farrell – John Butters 220 kV line & Farrell – Rosebery Tee Queenstown – Newton 110 kV line | TAS | | 22 | | 22 |
| Farrell – Sheffield No. 1 and No. 2 220 kV lines | TAS | | 9 | | 9 |
| Farrell Reece No. 1 and No. 2 220 kV lines | TAS | | 18 | | 18 |
| Norwood–Scottsdale–Derby 110 kV line and Norwood–Scottsdale 110 kV line | TAS | | 8 | | 8 |
| Tungatinah – New Norfolk tee Meadowbank No. 1 and No. 2 110 kV lines | TAS | | 2 | | 2 |
| Eildon – Mt Beauty No. 1 and No. 2 220 kV lines | VIC | | 14 | | 14 |
| Glenrowan – Dederang No. 1 and No. 3 220 kV lines | VIC | | 10 | | 10 |
| Loss of Alcoa Portland (APD) Potline 1 and Potline 2 | VIC | | | 1 | 1 |
| Rowville to Templestowe 220 kV line at the Templestowe end only | VIC | | | 1 | 1 |

A3. Non-credible contingency events, 1 May 2018 to 31 October 2018

Table 4 Non-credible contingency events, 1 May 2018 to 31 October 2018

| Date of contingency | Description | Region | Primary Cause | Was the contingency then reclassified? | Comments |
|------------------------|--|--------|--------------------------------------|--|--|
| 23/04/2018 1555 hrs | Trip of Loy Yang A3 and Pelican Point GT 12 and ST 18. | SA | Protection and Control | Yes | AEMO reclassified the event as a credible contingency for the loss of Pelican Point GT12 with any other generating unit on 23/05/2018 when Pelican units returned to service. AEMO considered the event was likely to reoccur until the issue was addressed. Engie advised that the cause of the trip was related to control system software issue. AEMO cancelled the reclassification on 27/05/2018 when the control system issue was rectified. |
| 3/05/2018 2348 hrs | Trip of Woree No.2 275/132 kV transformer 132 kV CB and offloaded Woree – Chalumbin 876 275 kV line | QLD | Protection and Control | No | Powerlink confirmed the trip was due to a faulty protection relay on the transformer. AEMO did not reclassify the event as the fault was rectified and unlikely to reoccur. |
| 9/05/2018 1017 hrs | Trip of the 330 kV 'A' busbar while performing planned maintenance on the Capital Wind Farm 33 kV busbar protection. | NSW | Human Error | No | TransGrid advised that the cause of trip was inadvertent trip signal being sent by staff working on Capital Wind Farm 330 kV C bus. TransGrid advised that the incident was unlikely to reoccur. |
| 14/05/2018 1204 hrs | Trip of two Tomago potlines | NSW | Human Error | No | The trip was due to operator error. AEMO did not reclassify the contingency as the cause was identified and unlikely to reoccur. |
| 22/05/2018 1001 hrs | Trip of Ross 275/132 kV No.2, 3, 4 Transformers and SVC. | QLD | Transmission Equipment Failure | No | Powerlink advised the trip was caused by a voltage transient on the 125V DC system due to wiring error in the circuitry. AEMO did not reclassify the event as the cause was identified and unlikely to reoccur. |
| 26/05/2018 0933 hrs | Trip of Strathmore No.1 and 2 132 kV buses. | QLD | Protection and Control | Yes | AEMO reclassified the trip of Strathmore 1 and 2 132 kV buses a credible contingency as the cause was not known when Strathmore buses returned to service. Powerlink advised that a fault occurred at Hamilton Solar, and two buses tripped due to incorrect wiring of the bus protection CT. AEMO cancelled the reclassification on the same day as the cause was identified and rectified. |

| Date of contingency | Description | Region | Primary Cause | Was the contingency then reclassified? | Comments |
|------------------------|---|--------|---------------------------|--|--|
| 28/05/2018 2221 hrs | Trip of Rowville – Templestowe 220 kV line at the Templestowe end only. | VIC | Protection and Control | Yes | AusNet advised the trip was due to inadvertent trip of the X protection however the cause was not determined when the protection was returned to service on 29/05/2018. AEMO reclassified the trip of the Rowville – Templestowe 220 kV line at the Templestowe end only as a credible event. The reclassification was cancelled on 03/06/2018 when the protection relay was replaced. |
| 14/06/2018 0126 hrs | Trip of APD Potline 1 and Potline 2. | VIC | Protection and Control | Yes | APD informed AEMO the cause was due to a 22 kV feeder fault. AEMO reclassified the loss of two potlines as a credible contingency as it was uncertain that a reoccurrence of the event was not reasonably possible. AEMO cancelled the reclassification when the issue was rectified on 19/06/2018. |
| 14/06/2018 0806 hrs | Trip of Wurdong No.1 275 kV busbar | QLD | Human Error | No | Powerlink advised the trip was due to insufficient isolation of protection systems during planned systems upgrade work. AEMO was satisfied that the cause had been identified and the incident was unlikely to reoccur. |
| 21/06/2018 1718 hrs | Trip of 996 Wagga 330 – ANM tee Morven 132 kV line at the Wagga end only. | NSW | Protection and Control | No | TransGrid advised the cause was a faulty relay at Wagga which was planned to be replaced on 22/06/2018. AEMO did not reclassify this event as TransGrid advised that the event was unlikely to reoccur. |
| 22/06/2018 0959 hrs | Trip of Pelican Point GT11, ST18, and reduced output of GT12. | SA | Protection and Control | Yes | On 17/03/2018 Pelican Point GT11 and ST18 tripped 38 seconds after Loy Yang tripped. On 22/06/2018 when GT11 returned for testing, AEMO reclassified the trip of Pelican Point GT11 and ST18 simultaneous with the trip of any other generating unit as credible as insufficient information was provided to confirm it would not reoccur for a similar power system event. During testing, GT11 tripped, and five minutes later ST18 tripped, and GT12 reduced in output. The trip of GT11 was related to bearing issue, and ST tripped due to condenser issue. AEMO later cancelled the reclassification on 29/06/2018 when the unit proved the fault ride through issue was resolved. |
| 2/07/2018 0755 hrs | Trip of Calliope River – Gin Gin (814) 275 kV line. | QLD | Protection and Control | No | Powerlink advised the trip was due to faulty protection operation during a planned switching of Larcom Creek – Calliope River 8859 275 kV line. The faulty protection was replaced and 814 line returned to service. AEMO did not reclassify the incident as the cause had been identified and rectified. |
| 13/07/2018 1633 hrs | Trip of Woree No.1 132 kV bus. | QLD | Protection and Control | No | Powerlink advised the trip was due to faulty bus protection relay operation. AEMO did not reclassify the incident as the cause had been identified and unlikely to reoccur. |
| 31/07/2018 1337 hrs | Trip of Nebo – Strathmore No. 878 and No. 8845 275 kV lines. | QLD | Human Error | No | The cause of trip was attributed to an earth wire on the 7125 line contacting conductors on the 878 and 8845 lines during planned work. AEMO did not reclassify the incident as the cause had been identified. |

| Date of contingency | Description | Region | Primary Cause | Was the contingency then reclassified? | Comments |
|------------------------|---|---------|--------------------------------------|--|--|
| 1/08/2018 1758 hrs | Simultaneous trip of Snuggery No.3 132/33 kV transformer and the Mount Gambier No.2 132/33 kV transformer. The trip of the Mount Gambier No.2 132/33 kV transformer offloaded the South East – Mount Gambier 132 kV line. | SA | Protection and Control | Yes | ElectraNet advised that the trip of Snuggery No. 3 transformer was due to a failed bushing. Mount Gambier transformer tripped due to Restrictive Earth Fault operated, and the Protection may not be stable. AEMO reclassified the trip of Mount Gambier No.2 132/33 kV transformer and another network element in the local 132 kV network as a credible contingency event as the cause of protection tripping was unknown. AEMO cancelled the reclassification on 10/08/2018 when the protection setting on the Mount Gambier No. 2 132/33 kV had been rectified. AEMO later identified that the event should not have been reclassified as Mount Gambier transformer and another network element in the local 132 kV network are not classified as transmission element. |
| 21/08/2018 0419 hrs | Trip of Calvale – Stanwell 855 275 kV line and Stanwell PS Unit 3. | QLD | Protection and Control | Yes | Stanwell advised the trip of Unit 3 was due to incorrect setting of Power Load Unbalance relay. The setting was updated later and Unit tested. AEMO cancelled the reclassification on 10/09/2018. |
| 25/08/2018 1312 hrs | Trip of Bulli Creek – Dumaresq 8L and 8M kV lines and separation of QLD and SA from the rest of the NEM. | NSW/QLD | Lightning | Yes | AEMO reclassified the trip of Bulli Creek – Dumaresq 1 and 2 lines as a credible contingency as the cause was not known. Powerlink confirmed that the cause was lightning strike to transmission infrastructure impacting two lines. AEMO cancelled the reclassification on the same day as the cause was identified. Reclassification decisions before and after the event were appropriate and consistent with the relevant reclassification criteria. |
| 2/09/2018 1144 hrs | Trip of Calvale – Gladstone Sth (7104) and Calvale – Gladstone Sth (7105) feeders. | QLD | Bushfire | No | Powerlink advised undetected grass fire went through easement. There was no hotspot detected by INDJI. The hotspot was reported by INDJI after the event occurred. AEMO had no justification to reclassify the loss of the two feeders as a credible contingency. These feeders were normally offloaded at Gladstone South ends. The cause of this non-credible contingency event had been identified and AEMO was satisfied that another occurrence of this event was unlikely. |
| 23/09/2018 1618 hrs | Trip of NEBO No.1 275 kV bus. | QLD | Human Error | No | Powerlink advised the bus trip was caused by insufficient isolation of protection systems on Nebo – Broadsound (8846) 275 kV line during planned work. Powerlink had identified the issue and advised the event was unlikely to reoccur again. |
| 9/10/2018 0647 hrs | Trip of the APD No.3 500 kV bus. | VIC | Protection and Control | No | APD advised the trip was caused by a mal operation of the protection on the APD A4 500/220 kV transformer. AEMO did not reclassify the event when the protection on APD A4 was rectified and return to service on the same day. |
| 23/10/2018 0618 hrs | Trip of the Stanwell – Broadsound No. 8831 275 kV line at Broadsound end only. | QLD | Transmission Equipment Failure | No | Powerlink advised the cause of the trip was due to faulty RTU controller card. AEMO did not reclassify the incident as the cause had been identified and rectified. |

| Date of contingency | Description | Region | Primary Cause | Was the contingency then reclassified? | Comments |
|------------------------|--|--------|---------------|--|--|
| 24/10/2018 1151 hrs | Trip of the Bouldercombe – Rockhampton (7107 and 7108) 132 kV lines. | QLD | Human Error | No | Powerlink advised the trip of 7107 & 7108 was caused by Ergon personnel working on a secondary control system (Ergon equipment). Powerlink advise that the trip of 7107 & 7108 was unlikely to reoccur. AEMO did not reclassify the event. |

A4. Market impact of reclassification constraints, 1 May 2018 to 31 October 2018

Table 5 Reclassification constraints that bound, 1 May 2018 to 31 October 2018

| Reclassification start time | Reclassification end time | Reclassified equipment | Constraint | Number of Dispatch Intervals binding |
|-----------------------------|---------------------------|--|----------------------|---|
| 4/05/2018 0555 hrs | 4/05/2018 0730 hrs | Farrell Reece No. 1 and No. 2 220 kV lines | F_T+FARE_N-2_RREG | 4 |
| 23/05/2018 1530 hrs | 27/05/2018 1115 hrs | Loss of Pelican Point GT 12 with any other generating unit | F_MAIN+NIL_MG_R60_PP | 808 |
| | | | F_MAIN+NIL_MG_R5_PP | 847 |
| | | | F_MAIN+NIL_MG_R6_PP | 831 |
| | | | N^^V_NIL_MAXG_PP_N-2 | 41 |
| 30/05/2018 1535 hrs | 30/05/2018 1640 hrs | Farrell – Sheffield No. 1 and No. 2 220 kV lines | F_T+FASH_N-2_TG_R6_2 | 5 |
| | | | F_T+FASH_N-2_TG_R6_1 | 12 |
| | | | F_T+FASH_N-2_TG_R6_4 | 1 |
| | | | F_T+FASH_N-2_RREG | 13 |
| | | | F_T+FASH_N-2_TG_R5 | 9 |

| Reclassification start time | Reclassification end time | Reclassified equipment | Constraint | Number of Dispatch Intervals binding |
|-----------------------------|---------------------------|--|----------------------|---|
| | | | F_T+FASH_N-2_TG_R60 | 6 |
| | | | F_T+FASH_N-2_TG_R6_3 | 1 |
| | | | T>T_FASH_1_N-2 | 1 |
| 14/06/2018 2145 hrs | 15/06/2018 0225 hrs | Farrell – Sheffield No. 1 and No. 2 220 kV lines | F_T++FASH_N-2_TG_R6 | 16 |
| | | | F_T+FASH_N-2_RREG | 9 |
| | | | F_T++FASH_N-2_TG_R60 | 17 |
| | | | F_T++FASH_N-2_TG_R5 | 13 |
| 22/06/2018 0935 hrs | 29/06/2018 1540 hrs | Loss of Pelican Point GT 11 with any other generating unit | F_I+NIL_MG_R5_PPN2 | 1078 |
| | | | F_I+NIL_MG_R60_PPN2 | 697 |
| | | | F_I+NIL_MG_R6_PPN2 | 714 |
| | | | F_MAIN++NIL_MG_R60_P | 979 |
| | | | F_MAIN++NIL_MG_R6_PP | 989 |
| | | | F_MAIN++NIL_MG_R5_PP | 795 |
| | | | N^^V_NIL_MAXG_PP_N-2 | 321 |
| | | | F_MAIN+NIL_MG_R6_PP | 68 |
| | | | F_MAIN+NIL_MG_R5_PP | 68 |
| | | | F_MAIN+NIL_MG_R60_PP | 68 |
| 19/07/2018 1105 hrs | 19/07/2018 1205 hrs | Farrell Reece No. 1 and No. 2 220 kV lines | F_T++FARE_N-2_TG_R6 | 4 |
| 31/07/2018 1550 hrs | 31/07/2018 1655 hrs | Farrell – Sheffield No. 1 and No. 2 220 kV lines | T>T_FASH_1_N-2 | 4 |
| 15/08/2018 0630 hrs | 15/08/2018 1030 hrs | Farrell Reece No. 1 and No. 2 220 kV lines | F_T++FARE_N-2_TG_R5 | 1 |
| 15/08/2018 0920 hrs | 15/08/2018 1150 hrs | Farrell – Sheffield No. 1 and No. 2 220 kV lines | F_T+FASH_N-2_RREG | 1 |
| | | | F_T++FASH_N-2_TG_R5 | 1 |
| | | | T>T_FASH_1_N-2 | 20 |
| | | | F_T++FASH_N-2_TG_R60 | 1 |
| 15/08/2018 1335 hrs | 15/08/2018 2105 hrs | Farrell – Sheffield No. 1 and No. 2 220 kV lines | T>T_FASH_1_N-2 | 11 |
| 15/09/2018 0250 hrs | 15/09/2018 0345 hrs | Farrell – Sheffield No. 1 and No. 2 220 kV lines | F_T+FASH_N-2_RREG | 11 |
| 15/09/2018 1630 hrs | 15/09/2018 1900 hrs | Farrell – Sheffield No. 1 and No. 2 220 kV lines | F_T+FASH_N-2_RREG | 18 |

| Reclassification start time | Reclassification end time | Reclassified equipment | Constraint | Number of Dispatch Intervals binding |
|-----------------------------|---------------------------|--|-------------------|---|
| | | | T>T_FASH_1_N-2 | 19 |
| 18/10/2018 1220 hrs | 18/10/2018 1320 hrs | Farrell – Sheffield No. 1 and No. 2 220 kV lines | F_T+FASH_N-2_RREG | 1 |